

Fixing Joists to the bearer:

Plas-Pro Subframe Screw, Hex Drive 90x6.3mm

Plas-Pro must always be pre drilled and also pilot holed

Step 1: (optional if head of fixing needs to be below the surface) Drill 15mm Dia. hole at an angle 10mm deep

Step 2: Pilot Hole 5mm Dia. Drill 60mm deep

Step 3: Relief Hole 8mm Dia. Drill all the way through the joist

Step 4: Drive screw in

Tip: Use of a counter bore bit will help speed these steps

